Please print or type. (Form designed for use on elite (12-pitch) typewriter.) Form Approved. OMB No. 2050-0039 3. Emergency Response Phone Manifest Tracking Number UNIFORM HAZARDOUS 1 Generator ID Number 2. Page 1 of **WASTE MANIFEST** 5. Generator's Name and Mailing Address Generator's Site Address (if different than mailing address) 2549 North New York Street CAME Wichita NS 67219 Generator's Phone: (316) 289 7400 6. Transporter 1 Company Name U.S. EPA ID Number 7. Transporter 2 Company Name U.S. EPA ID Number 8. Designated Facility Name and Site Address U.S. EPA ID Number Clean Harbors Env Services Inc NED981723513 2247 South Highway 71 Facility's Phone: MANAGE MANA 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, 10. Containers 9a. 11 Total 12. Unit 13. Waste Codes and Packing Group (if any)) HM Quantity Wt./Vol. No. Туре KA3077. HAZARDINIS WASTE. SOLID. N.O.S., (TOLUENE 0004 0000 DOGT LEADY, 9, PG III X 0000 0039 门的华的 14. Special Handling Instructions and Additional Information 1.CH921506K0B CHRT26497 15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true. Generator's/Offeror's Printed/Typed Name Month Year 16. International Shipments Import to U.S. J Export from U.S. Port of entry/exit/ Transporter signature (for exports only): Date leaving U.S.: 17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name Month Day Lossiel Geran Transporter 2 Printed/Typed Name Signature Month 18. Discrepancy 18a. Discrepancy Indication Space Quantity Residue Partial Rejection Full Rejection Manifest Reference Number: 18b. Alternate Facility (or Generator) U.S. EPA ID Number 18c. Signature of Alternate Facility (or Generator) Month Day Year 19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 1. 11040 4. 20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name Signature Month

Please print or type. (Form designed for use on elite (12-pitch) typewriter.) Form Approved. OMB No. 2050-0039 UNIFORM HAZARDOUS 1. Generator ID Number K S D G O 7 2 4 6 8 4 6 2. Page 1 of 3. Emergency Response Phone 4. Manifest Tracking Number (800) 483-3718 **WASTE MANIFEST** 5. Generator's Name and Mailing Address Generator's Site Address (if different than mailing address Ciean Harbors Kansas LLC 2549 Harth New York Street GAME Wichita, KS 67219 Generator's Phone: (316) 269-7400 6. Transporter 1 Company Name U.S. EPA ID Number MAD 039322250 8. Designated Facility Name and Site Address U.S. EPA ID Number Clean Harbors Env Services Inc NED981723513 2247 South Histhway 71 Facility's Phone 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, 9a. 10. Containers 11. Total 12. Unit and Packing Group (if any)) 13. Waste Codes НМ Quantity Wt./Vol. Type NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (TOLUENE, GENERATOR 0004 0005 0007 X LEAD), 9. PG III 25 1008 0039 0040 14. Special Handling Instructions and Additional Information 1.CH531506x0E ERS#171 CHRT 26497 15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true. Generator's/Offeror's Printed/Typed Name 16. International Shipments Import to U.S. Port of entry/exit Transporter signature (for exports only): Date leaving U.S.: 17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name Signature Lostal Bretui Transporter 2 Printed/Typed Name 18. Discrepancy 18a. Discrepancy Indication Space Туре Quantity Partial Rejection Full Rejection Manifest Reference Number 18b. Alternate Facility (or Generator) U.S. EPA ID Number Facility's Phone: 18c. Signature of Alternate Facility (or Generator) Month Day 19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) H040 20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name Signature

298450

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS 1. Generator ID Number K S D 0 0 7 2 4 6 8 4 6 3. Emergency Response Phone 2. Page 1 of 1 (800) 483-3718 WASTE MANIFEST 5. Generator's Name and Mailing Address Clean Harbors Kansas LLC Generator's Site Address (if different than mailing address) 2549 North New York Street SAME Wichita, KS 67219 Generator's Phone: (316) 269-7400 6. Transporter 1 Company Name U.S. EPA ID Number MAD 039322250 Env Secvices Inc -leap 8. Designated Facility Name and Site Address U.S. EPA ID Number Clean Harbors Env Services Inc NED981723513 2247 South Highway 71 Kimball. NE 69145 Facility's Phone: (308) 235-4012 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, 10. Containers 11 Total 12 Unit 13. Waste Codes and Packing Group (if any)) HM No. Type Quantity Wt./Vol. NA3077. HAZARDOUS WASTE, SOLID, N.O.S., (TOLUENE, D004 D005 D007 GENERATOR 25 X LEAD), 9, PG III 001 0008 D040 D039 14. Special Handling Instructions and Additional Information 1.CH831506X0B ERG#171 CHRT 26497 15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true. Generator's/Offeror's Printed/Typed Name 16. International Shipments Port of entry/exit Import to U.S. Date leaving U.S.: Transporter signature (for exports only): 17. Transporter Acknowledgment of Receipt of Materials TR ANSPORTER Transporter 1 Printed/Types Name Month Year Transporter 2 Printed/Typed Nar 18. Disareponcy 18a. Discrepancy Indication Space Туре Quantity Residue \_\_ Partial Rejection Full Rejection Manifest Reference Number: 18b. Alternate Facility (or Generator) U.S. EPA ID Number DESIGNATED FACILITY Facility's Phone: 18c. Signature of Alternate Facility (or Generator) Month Day Year 19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) H040 20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name Signature 09/12/14 1 homas EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete. DESIGNATED FACILITY TO DESTINATION STATE (IF REQUIRED)

05 190



2247 South Highway 71 Kimball, NE 69145

TEL 308-235-4012 FAX 308-235-4307 www.cleanharbors.com

DATE:

9/12/2014

MANIFEST:

007024772FLE

Dear Valued Customer:

In accordance with 40 CFR 264.12(b), Clean Harbors Environmental Services, Inc., Kimball Facility, has appropriate state and federal permits to accept, store, and/or treat the waste you shipped to our facility. This letter should be kept on file with your copy of the signed manifest.

Clean Harbors Environmental Services, Inc. makes every effort to ensure that signed copies of manifests are returned to the waste generator as quickly as possible following receipt of your waste at our facility. This allows us to provide you with rapid verification that your waste shipment arrived safely at our waste management facility.

Once your waste has been received, Clean Harbors' personnel will verify that the quantity that has been received matches the quantity that was shipped. We also inspect the material and conduct testing to ensure that it meets the facility's waste acceptance criteria as described in our Waste Analysis Plan, as well as processing requirements. Every effort is made to complete the waste verification as quickly as possible; however, it is possible that the signed copy of the manifest may be returned to you before the waste verification process is completed. If a significant discrepancy, as defined by US EPA regulations (40 CFR 264.72), is discovered during the waste verification process, we will contact you in order to reconcile the discrepancy. Additionally, we will work with you to make any corrections to the waste manifest that are necessary.

Sincerely,

Receiving Department